

# Updates to System 64 Training Trailer

31 January 2025



**MFSI has replaced the 200 lbs. propane prop used with the System 64 trailer for a total investment of \$5,000 in order to keep our training equipment in optimal working condition.**

## NEW PROP



## COOL THE PROP:

Please ensure that the cooling line is properly utilized to prevent potential damage.

Additionally, in the event of a delay in cooling the prop –whether due to a student or mechanical issue – **please thoroughly cool the prop** using a hose stream. This extra precaution will help prevent warping and the breaking of welds.

## SECURE THE PROP:

Each leg of the propane prop features a hole through which a pin can be inserted. **Please ensure that the propane prop is securely fastened to the burn pan.**



## OLD PROP: Notice warping



Pictured: Broken weld on old prop due to excessive heat with no cooling of hand lines.



Securing the prop in place is essential to prevent rocking. **Please properly secure all four sides of the prop and ensure that all four pins are in place.**

**Should you notice any issues, contact us so that we can address the problem promptly.**

[mfsisupport@maineccc.edu](mailto:mfsisupport@maineccc.edu)

207-844-2072